



Dart Aerospace Ltd.
1270 Aberdeen St
Hawkesbury, ON
K6A 1K7
Canada

Tel (613) 632-5200
Fax 613 632-5246

D4122-3

Job Sheet 203221



Part No: D4122-3

Job Qty: 1 pcs

Part Name: Floor Protector, Aft



Part Weight: 0 lbs

Status: New

Priority: Medium

Job Created: 11/13/19

Job Tracking No:

Created By: Marie Lajeunesse

Due Date: 11/19/19

Description:

Type: SOLD

Note: DWG REV B IPP Rev:A 10.06.04 new issue DD verf:JLM IPP Rev:B 10.10.14 AS PER REV.B DD verf:JLM

Ship Via:

Bill of Materials

Job Routing

Op No	Operation	Qty	Start Date	Due Date	Standard		Workcenter/Supplier		Sign-off
					Setup Hrs	Run Hrs	Workcenter / Supplier	Lead Time	
100	Waterjet - Flow - 1	1 pcs	11/19/19	11/19/19	0.17	0.31	Waterjet - Flow		SRB 11/14/19
110	QC 2	1 pcs	11/19/19	11/19/19	0.00	0.00	QC 2 - 1		
							QC 2 - 12		
							QC 2 - 14		
							QC 2 - 17		
							QC 2 - 19		
							QC 2 - 2		
							QC 2 - 20		
							QC 2 - 22		
							QC 2 - 23		
							QC 2 - 25		
							QC 2 - 32		
							QC 2 - 33		
							QC 2 - 35		
							QC 2 - 39		
							QC 2 - 4		
							QC 2 - 40		
							QC 2 - 44		
							QC 2 - 45		
							QC 2 - 48		
							QC 2 - 49		
							QC 2 - 50		
							QC 2 - 51		
							QC 2 - 52		
							QC 2 - 57		
							QC 2 - 62		
							QC 2 - 63		
							QC 2 - 8		
							QC 2 - 66		
							QC 2 - 64		
							QC 2 - 65		

PRIORITY

Dart Aerospace Ltd.
1270 Aberdeen Street
Hawkesbury, ON K6A 1K7
CANADA
Tel: 1 613 632-5200
Email: sales@dartaero.com
www.dartaero.com

Container No: S232015

Part: D4122-3

Job No: 203221

Serial No/Batch: S232015

Revision:

Inspector:

Exp Date:

Instructions: Various STC's

Date: 11/14/19

120 QC 8	1 pcs	11/19/19	0.00 0.00	QC 2 - 5	
				QC 2 - 71	
				QC 2 - 73	
				QC 2 - 69	
				QC 8 - 12	
				QC 8 - 14	
				QC 8 - 17	
				QC 8 - 20	
				QC 8 - 25	
				QC 8 - 3	
				QC 8 - 32	
				QC 8 - 33	
				QC 8 - 35	
				QC 8 - 39	
				QC 8 - 4	
				QC 8 - 44	
				QC 8 - 45	
				QC 8 - 49	
				QC 8 - 58	
				QC 8 - 8	
				QC 8 - 9	
				QC 8 - 68	
				QC 8 - 67	
				QC 8 - 1 (A)	
				QC 8 - 47	
				QC 8 - 40	
				QC 8 - 52	
				QC 8 - 23	
				QC 8 - 57	
				QC 8 - 76	
				QC 8 - 61	
130 Small Fab - 2 - B4B	1 pcs	11/19/19	0.00 0.10	Small Fab - 1 - B4B	
				Small Fab - 2 - B4B	
				Small Fab - 3 - B4B	
				Small Fab - 4 - B4B	
				Small Fab - 5 - B4B	
				Small Fab - 6 - B4B	
				Small Fab - 7 - B4B	
				Small Fab - 8 - B4B	
				Small Fab - 9 - B4B	
140 QC 5	1 pcs	11/19/19	0.00 0.00	QC 5 - 10	
				QC 5 - 12	
				QC 5 - 17	
				QC 5 - 18	
				QC 5 - 19	
				QC 5 - 22	
				QC 5 - 24	
				QC 5 - 3	
				QC 5 - 43	
				QC 5 - 49	
				QC 5 - 51	
				QC 5 - 58	
				QC 5 - 68	
				QC 5 - 9	
				QC 5 - 50	
				QC 5 - 30	
				QC 5 - 40	
				QC 5 - 61	
				QC 5 - 81	

JRB 11/14/19

DAS
NOV 15 2019 40
8-89DAS
NOV 18 2019 68
9-89

150 Packaging 3-1 - Stock - B4B 1 pcs

11/19/19

0.00 0.00

Packaging 3 - 1 - B4B

Packaging 3 - 2 - B4B

Packaging 3 - 3 - B4B

Packaging 3 - 4 - B4B

Packaging 3 - 5 - B4B

Packaging 3 - 6 - B4B

Packaging 3 - 7 - B4B

Packaging 3 - 8 - B4B

Packaging 3 - 9 - B4B

Packaging 3 - 10 - B4B

Packaging 3 - 11 - B4B

Packaging 3 - 12 - B4B

Packaging 3 - 13 - B4B

Packaging 3 - 14 - B4B

Packaging 3 - 15 - B4B

Packaging 3 - 16 - B4B

Packaging 3 - 17 - B4B

Packaging 3 - 18 - B4B

Packaging 3 - 19 - B4B

Packaging 3 - 20 - B4B

Packaging 3 - 21 - B4B

Packaging 3 - 22 - B4B

Packaging 3 - 23 - B4B

Packaging 3 - 24 - B4B

Packaging 3 - 25 - B4B

Packaging 3 - 26 - B4B

Packaging 3 - 27 - B4B

Packaging 3 - 28 - B4B

Packaging 3 - 29 - B4B

Packaging 3 - 30 - B4B

Packaging 3 - 31 - B4B

Packaging 3 - 32 - B4B

Packaging 3 - 33 - B4B

Packaging 3 - 34 - B4B

Packaging 3 - 35 - B4B

Packaging 3 - 36 - B4B

DAS
28
9-89

160 QC 21 - SA

1 pcs

11/19/19

0.00 0.00

QC 21 - SA - 21

QC 21 - SA - 70

QC 21 - SA - 53

DAS
21
9-89

NOV 19 2019

Part Op 100 - 1-Cut as per Dwg Dwg Rev: BProg Rev: B

2-Deburr if necessary

Descriptions: 110 - (QC2- Inspect parts off machine FAI/FAIB)

120 - (QC8- Inspect parts - second check)

130 - (Small Fab) Deburr if necessary.

140 - (QC5- Inspect part completeness to step on W/O)

150 - (Identify as per dwg & Stock Location: _____)

160 - (QC21- Final Inspection - Work Order Release)

Job BOM

Part / Item	Component Name	Quantity	Operation	Container
MLEXS.125-F60029-04	GE Plastics Lexan Sheet (Dark Grey)	8.8030 sf (8.803 ea)	100-Waterjet - Flow - 1	5152065-1

Job Allocations

Operation	Component Part	Required	Inventory	Allocated
100-Waterjet - Flow - 1	MLEXS.125-F60029-04	9	1,138	0

Part Specifications

Specifications could not be found.

Entered: _____ Date: _____

WORK ORDER NON-CONFORMANCE / ROUTE UPDATE

NCR No. _____

Route update only ☐

Job: _____ Part No. _____		DISPOSITION		DEPARTMENT/PROCESS																																																											
		Rework Scrap Use-as-is		Cross tube Small Fab Finishing		Eng. (Non-AW) Prod. Eng. Coord. Rec/Store/Packaging		Engineering Water Jet Supplier Quality																																																							
Date :		Sequence #:		QTY Affected :		MRB (QS1042)																																																									
Description Work Order Deviation				Disposition																																																											
Root Cause <table border="1"><tr><td>Operator</td><td></td></tr><tr><td>Manufacturing Process</td><td></td></tr><tr><td>Equip/Tooling</td><td></td></tr><tr><td>Handling/Preservation</td><td></td></tr><tr><td>Material</td><td></td></tr><tr><td>Product Improvement</td><td></td></tr><tr><td>Process Improvement</td><td></td></tr><tr><td>Human Factors</td><td></td></tr></table>				Operator		Manufacturing Process		Equip/Tooling		Handling/Preservation		Material		Product Improvement		Process Improvement		Human Factors		FAULT CATEGORY																																											
				Operator																																																											
				Manufacturing Process																																																											
Equip/Tooling																																																															
Handling/Preservation																																																															
Material																																																															
Product Improvement																																																															
Process Improvement																																																															
Human Factors																																																															
<table border="1"><tr><td>Pressure/Forced</td><td></td><td>Contamination</td><td></td><td>Power Loss/Surge</td><td></td><td>Positioned Wrong</td><td></td></tr><tr><td>Bending</td><td></td><td>Misaligned/off center</td><td></td><td>Folio/Program</td><td></td><td>Outside Tolerance</td><td></td></tr><tr><td>Crushing</td><td></td><td>BOM/Route</td><td></td><td>Grain Direction</td><td></td><td>Drawing</td><td></td></tr><tr><td>Cracks</td><td></td><td>Broken/Damage/Defect</td><td></td><td>Weld</td><td></td><td>Finish</td><td></td></tr><tr><td>Crimp/Kink/Ripple/Wave/Twist</td><td></td><td>Incomplete/Unclear Instructions</td><td></td><td>Wrong Stock Pulled</td><td></td><td>Part Lost/Missing</td><td></td></tr><tr><td>Marks/Chatter</td><td></td><td>Drill Holes</td><td></td><td>Out of Sequence</td><td></td><td>Misread</td><td></td></tr><tr><td>Mislabeled</td><td></td><td>Fit/Function</td><td></td><td>Off-set/Set-up</td><td></td><td></td><td></td></tr></table>						Pressure/Forced		Contamination		Power Loss/Surge		Positioned Wrong		Bending		Misaligned/off center		Folio/Program		Outside Tolerance		Crushing		BOM/Route		Grain Direction		Drawing		Cracks		Broken/Damage/Defect		Weld		Finish		Crimp/Kink/Ripple/Wave/Twist		Incomplete/Unclear Instructions		Wrong Stock Pulled		Part Lost/Missing		Marks/Chatter		Drill Holes		Out of Sequence		Misread		Mislabeled		Fit/Function		Off-set/Set-up				Completed By	
Pressure/Forced		Contamination		Power Loss/Surge		Positioned Wrong																																																									
Bending		Misaligned/off center		Folio/Program		Outside Tolerance																																																									
Crushing		BOM/Route		Grain Direction		Drawing																																																									
Cracks		Broken/Damage/Defect		Weld		Finish																																																									
Crimp/Kink/Ripple/Wave/Twist		Incomplete/Unclear Instructions		Wrong Stock Pulled		Part Lost/Missing																																																									
Marks/Chatter		Drill Holes		Out of Sequence		Misread																																																									
Mislabeled		Fit/Function		Off-set/Set-up																																																											
						Lead hand / Supervisor																																																									
						QC / QA Coordinator																																																									